EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	150	strain near4 relax$4.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 16:25
L2	1	1 and lamella	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 18:29
L3	17	1 and interface.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 16:47
L4	1233	(73/800-804).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/10/30 18:29
L5	1	4 and lamella	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 18:30
L6	2	1 and 4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 18:30
S1	334455	(composite polymer).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/29 14:30
S2	4695	S1 and (phase near2 (plurality two second three four many several array multipl$5 couple double pair another)).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/29 14:31

EAST Search History

S3	2	S2 and strain near2 relax$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 09:49
S4	1996	strain near2 relax$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 10:21
S5	6	S4 and ((deforamtion rotation) near3 (measur$5 indicat$4 meter$4 test$4 detect$4 determin$4 sens$4 identi$6 evaluat$5 estimat$5 transducer gauge cell monitor$4 comput$5 inspect$5 meter calculat$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/10/30 10:21
S6	2914	strain near4 relax$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 10:21
S7	150	strain near4 relax$4.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/10/30 16:25
S8	11	S6 and ((deforamtion rotation) near3 (measur$5 indicat$4 meter$4 test$4 detect$4 determin$4 sens$4 identi$6 evaluat$5 estimat$5 transducer gauge cell monitor$4 comput$5 inspect$5 meter calculat$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/10/30 10:25
S9	1	S7 and ((deforamtion rotation) near3 (measur$5 indicat$4 meter$4 test$4 detect$4 determin$4 sens$4 identi$6 evaluat$5 estimat$5 transducer gauge cell monitor$4 comput$5 inspect$5 meter calculat$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/10/30 10:27